

11-5-02

Hereinover Lead Smelter

To-27

0630 Steve Schuler leaves office

0735 Arrive on Site, present already is OSC Silver. The weather this AM is wet & rainy. High's today will be in the 50's. Activities today will include:

① Shoot soil samples of the Nation as part of the Recontamination soil sampling. ② Begin preparation of the Interim Report.

③ ^{PCS} ~~LOA~~ LETTERS generated for 196, 200, & 202 Dunlin - explaining that their yards are clean.

0900 Reno loads software for new printer on OSC Silver's computer

0930 Schuler updates logbook, and begins to shoot soil samples. - (unlabeled)

1000 - Schuler calls Cannon customer support to install MULTIPASS (printer/fax) software on his PC.

1130 - Finishing off phone with many difficulties

A117

40499120



Superfund

2.0

0100

11-5-02

Herndon Lead Sheet

Page 27

1200 lunch.

1230 Schuler shoots 200m Samples. -

Reno changes database.

1430 SAME AS ABOVE, ER is not working today. - MODN 123 matt office confirms this with his observations.

Schuler leaves site. Reno continues modifying the database.

1600 Reno leaves site

Lab entry - 1500 - Schuler leaves site

1630 Schuler arrives at office